


# Dimensional Documentation

**viega**




## Bronze Adapter P x MPT - Model 2911ZL



Part Number	Size		A (in)	L (in)
	1	2		
79210	1/2"	3/8" MPT	0.77	1.59
79215	1/2"	1/2" MPT	0.89	1.71
79220	1/2"	3/4" MPT	1.00	1.83
79225	3/4"	1/2" MPT	1.02	1.93
79230	3/4"	3/4" MPT	1.02	1.93
79235	3/4"	1" MPT	1.18	2.09
79240	1"	3/4" MPT	1.18	2.09
79245	1"	1" MPT	1.26	2.17
79250	1"	1 1/4" MPT	1.54	2.44
79255	1 1/4"	1" MPT	1.22	2.24
79260	1 1/4"	1 1/4" MPT	1.34	2.36
79265	1 1/4"	1 1/2" MPT	1.48	2.50
79270	1 1/2"	1 1/4" MPT	1.34	2.76
79275	1 1/2"	1 1/2" MPT	1.28	2.70
79280	1 1/2"	2" MPT	1.65	3.07
79285	2"	1 1/2" MPT	1.54	3.11
79290	2"	2" MPT	1.50	3.07

## Bronze Adapter P x FPT - Model 2912ZL



Part Number	Size		A (in)	L (in)
	1	2		
79295	1/2"	3/8" FPT	0.19	1.42
79300	1/2"	1/2" FPT	0.25	1.61
79305	1/2"	3/4" FPT	0.27	1.65
79310	3/4"	1/2" FPT	0.32	1.77
79315	3/4"	3/4" FPT	0.35	1.81
79320	1"	1/2" FPT	0.41	1.85
79325	1"	3/4" FPT	0.39	1.85
79330	1"	1" FPT	0.44	2.01
79335	1"	1 1/4" FPT	0.50	2.09
79340	1 1/4"	1/2" FPT	0.37	1.93
79345	1 1/4"	1" FPT	0.24	1.93
79350	1 1/4"	1 1/4" FPT	0.34	2.05
79355	1 1/4"	1 1/2" FPT	0.42	2.13
79360	1 1/2"	1 1/4" FPT	0.26	2.36
79365	1 1/2"	1 1/2" FPT	0.34	2.44
79370	2"	2" FPT	0.41	2.68